DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453

(707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-009505

Address: 333 Burma Road **Date Inspected:** 15-Sep-2009

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Sun Bo **CWI Present:** Yes No Yes **Inspected CWI report:** N/A **Rod Oven in Use:** Yes No No N/A Yes N/A N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS: Delayed / Cancelled:** Yes No N/A

34-0006 **Bridge No: Component: OBG Deck Panels**

Summary of Items Observed:

On this day Caltrans OSM Quality Assurance (QA) Inspector Stefan Holmes was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhen Hua Port Machinery Company (ZPMC) at Chang Xing Island in Shanghai, China.

QA inspector performed conventional Ultrasonic (UT) Inspection on deck panel tack weld areas. The inspection is preliminary prior to using the phased array (PAUT) testing system to verify indications found with conventional Ultrasonic testing. QA inspector performed UT on deck panel DP375-001, 5 ribs, 10 welds, 280 total tack welds inspected.

Weld 1 scanned 28 locations with 0 indications.

Weld 2 scanned 28 locations with 1 indications.

Weld 3 scanned 28 locations with 1 indications.

Weld 4 scanned 28 locations with 1 indications.

Weld 5 scanned 28 locations with 0 indications.

Weld 6 scanned 28 locations with 5 indications.

Weld 7 scanned 28 locations with 0 indications.

Weld 8 scanned 28 locations with 0 indications.

Weld 9 scanned 28 locations with 1 indications.

Weld 10 scanned 28 locations with 1 indications.

All indications for further inspection by PAUT are marked on top of u-ribs. Please see U-rib Deck Panel Tack

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Weld Assessment sheet dated 15 September, 2009 for specific locations of indications.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact, who represents the Office of Structural Materials for your project.

Inspected By:	Holmes,Stefan	Quality Assurance Inspector
Reviewed By:	Hall,Steven	QA Reviewer